

#TB2017-003

**Subject:** Seat Belt Recall

**From:** Rick Parent, Technical Director

**Date:** June 26 2017



Safety & Recall Notice

To All Distributors & Consumers

4/28/17

**Corbeau USA, LLC 5-Point Camlock Harness Belt Recall (53001B, 53007B, 53009B)**

**TO:** All Corbeau USA, LLC Dealers, and Consumers

**FROM:** Corbeau USA, LLC, Bluffdale, UT, USA

Corbeau USA, LLC has recently discovered a potential safety issue with its 5-Point Camlock Harness Belts. We have reason to believe that on a small percentage of belts, the right lap insert tab had the hole drilled off center by a 1/16th of an inch, causing the lock pin inside the camlock dial to not lock properly. This could potentially cause the right lap belt to come unlocked from the camlock dial under minimal stress.

Corbeau USA, LLC is voluntarily recalling 5-Point camlock harness belts with part numbers 53001B, 53007B, and 53009B purchased between 4/01/16 and 4/24/17. These would have stamp dates between May 2016 and May 2017. In other words, all belts with SFI stamp dates from May 2016 to June 2017 are being recalled. This does not include any belts purchased after 4/24/17. We are certain this only applies to a very small percentage of these belts but at the same time also want to be certain that all belts in the field are free from this defect. The problem was found during testing with the SFI foundation. This recall ONLY applies to 5-Point camlock harness belts. While we are certain this only applies to a small percentage of belts, we ask that you please contact us immediately to return your belts so there are no doubts that your belts are free from defect.

**North American Consumer Instructions:**

STOP using your 5-Point camlock harness belt immediately and call Corbeau customer service at 801-255-3737 or email [info@corbeau.com](mailto:info@corbeau.com) to receive a return authorization number for your harness belt. We will need to know when and where your harness belt was purchased and how much you paid. Corbeau USA, LLC will pay to have your belt returned and it will either be fixed or a new belt will be sent out immediately. All shipping costs will be handled by Corbeau USA, LLC. Please call customer service at 801-255-3737 should you have any questions or concerns.

**North America Dealer Instructions:**

Corbeau 5-Point camlock harness belts purchased and or sold between 3/1/16 and 4/24/17 need to be returned for inspection immediately. If you have not already spoken with a representative from Corbeau USA, LLC, please call us immediately at 801-255-3737 to review how many belts you sold and how to best inform your customers. We are happy to call customers direct to inform them of the recall process.

© Copyright Corbeau® USA, LLC. 1990-2017. All rights reserved.

PO Box 708038 • Sandy, UT 84070 • Tel: 801-255-3737 • Email: [info@corbeau.com](mailto:info@corbeau.com)

